



**37<sup>TH</sup> INTERNATIONAL  
No-DIG  
FLORENCE 2019**

**Fortezza da Basso • FLORENCE (Italy)**

**30<sup>th</sup> September • 2<sup>nd</sup> October 2019**

Unique Horizontal Drain Installation under a Building  
Using Pilot Tube Guided Auger Bore Methods

Michelle Macauley - Macauley Trenchless  
Steve Torgerson - Trenchless Construction Services



# AGENDA


- History of the site
- Trenchless considerations
- Trenchless design
- Pre-construction
- Construction
- Lessons learned





# History of the site




- Built in the 1960s in a flood plain
- Additions added over decades at different elevations
- Original design included waterproof membranes, sub-slab drainage, and perimeter drains
- Subsequent additions experienced flooding





# Past Solutions for Flooding

- Vertical dewatering wells installed around perimeter in 1990s
- Worked well until 2010
- Investigation found that the wells had reduced capacity due to being fouled with iron-fixing bacteria
- Additional wells were installed in 2014 but only worked for a few years

Contractor/Crew: Layne				Date Started: 8/23/11		Date Completed: 8/23/11			
Drilling Method: Rotasonic				Elevation (ft): 0		Total Depth (ft): 45		Depth to Water (ft): 17	
Depth (ft)	Sample Interval	Recovery	PID (ppm)	Description		Profile	Remarks Lab Samples, etc.		
0	0-10'	2'		Sand, coarse, brown, (fill) <div>Sand</div>			Hole was hydro vac'd to 8' on 8/22/11 and backfilled with coarse sand		
- 2									
- 4									
- 6									
- 8	10-20'	2'							
- 10									
- 12									
- 14									
- 16				Sand, medium-coarse, with few fine rounded gravel, brown <div>Sand</div>			The boring was 25' north of well DW-4 which was active at the time the water level was measured		
- 18									
- 20									
- 22									
- 24	20-30'	2'							
Proposed Drain Elevation									



# Trenchless Considerations




- 400-foot installation length
- Both 6-inch and 10-inch diameter installations
- No construction access inside the building during horizontal drain installation
- Granular soils with a high groundwater level
- Installed well screen needed to be robust to allow for post-installation (long-term) cleaning.



# Trenchless Options

- Horizontal Directional Drilling
  - Settlement potential with overcut borehole
  - Low accuracy (no access to building)
  - Curvature of pullback could damage drains
- Auger Boring
  - Low accuracy
  - Oversize casing
- Pilot Tube Guided Auger Boring
  - Very accurate
  - Unique install w/oversize casing






SOQ 2005, DTD Inc,



# Benefits of Pilot Tube Guided Auger Bore



- All steering and guidance is located in the launch pit
- Straight pit-to-pit installation method, no curves
- No drilling fluid is typically used during installation that could foul the well screens
- The amount of over-cut is considerably smaller than HDD, which reduces the potential for settlement



Pilot tube process from Bohrtec website




# Trenchless Design





# Trenchless Design






# Pre-Construction Considerations



37<sup>TH</sup> INTERNATIONAL  
**NO-DIG**  
FLORENCE 2019

- Contractor submits a change
  1. Pilot tube install
  2. Follow with sizing tool
  3. Product pipe jacked
- Trenchless work plan indicating:
  - the equipment layout
  - the reaction wall locations for each splay within the shoring and
  - the well casing/ adapters
- Pre-Construction verification of screen strength
  - Expect minimal increase in jacking force (7 3/8" vs 6")
  - Pre-construction testing of screen strength
  - Johnson Screens on-site
- Typically cannot reverse, except in pilot mode





# Specialty Adapters




37<sup>TH</sup> INTERNATIONAL  
**NO-DIG**  
FLORENCE 2019




FRONT VIEW

**APPROXIMATE WEIGHT OF PART**  
**46 POUNDS**



ITEM: Male Flush Thread  
7 1/4" O.D. x 12" Long  
MAT'L: 1045 STEEL  
QTY: 1

PILOT TUBE ADAPTER  
"GERMAN THREADED PIPE"  
STUB ACME THREAD  
4 TPI  
Ø5.305" Major Diameter  
Ø5.180" Minor Diameter  
Ø5.243" Pitch Diameter  
0.125" Groove Width




DETAIL B  
O-Ring Groove

JOHNSON SCREEN ADAPTER  
MALE FLUSH THREAD  
2 TP1  
Ø6.393" ± 0.003" Major Diameter  
Ø6.283" ± 0.003" Minor Diameter  
0.255" ± 0.003" Groove Width



REAR VIEW



NEEDS 1 EACH 5" THREADED PIPE PLUG  
PIPE PLUG MUST HAVE 1" NPT PIPE  
THREAD AND THRU HOLE IN CENTER



FRONT VIEW





- Delays
  - Mobilized November 26th (in Minnesota)
- Order of construction
  1. Excavate launch shaft
  2. Additional dewatering
  3. Storm drain line install
  4. Excavate the launch shaft further
  5. HD 4 through HD 1



**Added complication:  
Looming Government Shutdown  
starting December 22nd**



# Storm Drain

- Started on November 28th
  - Anticipated high quantities of groundwater
  - Planned to use water auger
  - Encountered clay, which plugged auger
  - Jacking forces climbed
  - Water soluble lubricant clumped and caused system to repeatedly plug
  - Switched to regular bentonite-based lubricant since storm drain wasn't a drain --- Jacking forces reduced
- 2 days for pilot tube installation, 2 days for auger/casing, 2 days for 10-inch drain installation





# Storm Drain Construction





# Horizontal Drains 4 and 3





37<sup>TH</sup> INTERNATIONAL  
**NO - DIG**  
FLORENCE 2019

- HD 4
  - Started on December 10th
  - Went very well
  - 3 days for horizontal drain installation
- HD 3
  - Started on December 13th
  - Went very well
  - 2 days for horizontal drain installation







# Horizontal Drains 4 and 3





# Horizontal Drains 4 and 3





# Horizontal Drain 2

- Started on December 15th
- Very oblique angle. The waler near the bottom of the excavation resulted in a long section of exposed pipe
- Within 15 feet of progress, well casing became cross-threaded
- Tried to pull casing, even though machine not geared for it; damaged pipe further
- Tried innovative approach to push the damaged drain casing out





## Horizontal Drain 2




- Innovative approach
  - Cut off exposed tail end of horizontal drain
  - Cut off threaded end of pilot tube resulting in a blunt end
  - Pilot tube was pushed inside remaining (damaged) portion of the horizontal drain
  - Pilot tube then pushed damaged section of drain screen out of the alignment

## Horizontal Drain

## Adapter

## Pilot tube





# Horizontal Drain 2 Conclusions

- Unexpected benefit: the damaged section of screen acted like an HDD pre-ream
- The installation of second screen was very easy
- Entire installation took 4 days
  - With a quick trip to Johnson Screen





# Horizontal Drain 1

- Started December 20th (two days before government shutdown)
- Last one: went very well
- Finished just in time
- Drove off with 26 minutes to spare before mandatory site closure due to government shutdown








- Cross-over adapter: Make with tool steel, not mild steel
- Shoring system: Waler placement is important
  - Caused jacking frame placement too far from the wall
  - Caused an increase in exposed drain pipe length
  - Created unforeseen lateral forces on the drain pipe, especially for the more oblique installations
- Dewatering contractor: should be required to provide drawdown curves showing the construction dewatering area of influence so the trenchless contractor can better plan for conditions



# Jacking Forces





Thank you



Michelle Macauley  
Macauley Trenchless  
**[michelle@macauleytrenchless.com](mailto:michelle@macauleytrenchless.com)**



Steve Torgerson  
Trenchless Construction Services  
**[st@trenchlessconstruction.com](mailto:st@trenchlessconstruction.com)**

