



**37TH INTERNATIONAL
NO - DIG
FLORENCE 2019**

Fortezza da Basso • FLORENCE (Italy)

30th September • 2nd October 2019

FRP 101: Taking The Mystery out of Trenchless Repair of Pressure Pipes with Carbon FRP

***Mo Ehsani, PhD, PE
Professor Emeritus of Civil Eng., U. of Arizona
President/CEO QuakeWrap Inc., Tucson, AZ***

Introduction



- History of Development
- Application to Pipes


Fiber Reinforced Polymer (FRP)

Why is it called FRP?

- A Polymer (i.e. epoxy, vinyl ester, etc.) reinforced with a Fiber (e.g. carbon, glass, etc.)
- FRP does not have the same strength in all directions (*anisotropic*)

Reinforcing Fiber

(Glass, Carbon, Kevlar, etc.)




QuakeWrap® FRP Products



Comparison of FRP and Steel



37TH INTERNATIONAL
NO - DIG
FLORENCE 2019



Advantages of FRP



37TH INTERNATIONAL
NO - DIG
FLORENCE 2019

- High Tensile Strength (*3-5 times stronger than Steel*)
- Low Weight (*no foundation adjustments required*)
- Corrosion Resistance & Protection
- Chemical Protection
- Waterproof
- Speed of Construction
- Versatility
- Odorless & Non-Toxic (QuakeWrap Products)
- NSF-61 Certified for pipes ≥ 8 inches
- Minimal Investment




History of FRP in other Industries

Corvette C1 - 1953




Materials used in 787 body

- Fiberglass
- Aluminum
- Carbon laminate composite
- Carbon sandwich composite
- Aluminum/steel/titanium



**Total materials used
By weight**



By comparison, the 777 uses 12 percent composites and 50 percent aluminum.

100% FRP Hull



Original Concept Demonstration (1987)

Carbon FRP instead of reinforcing steel



37TH INTERNATIONAL
NO - DIG
FLORENCE 2019



Loma Prieta Earthquake Oct 1989

Failure of R/C Columns



37TH INTERNATIONAL
NO - DIG
FLORENCE 2019



Indiana Bridge

Indiana Project R-27862-A – SR 49



37TH INTERNATIONAL
NO-DIG
FLORENCE 2019



Sample Projects



Testing + R&D



Condo, FL



Statue of Liberty



Bridge, NM



Settling Tank, MX



UN Lebanon



High Rise, AK



Pipe, Costa Rica




Kazakhstan

Cell Phone Tower Strengthening




Design for Internal Pressure



**Carbon
Fabric**

Thickness: 0.05 in. (1.3 mm)
Weight: 0.38 lb/ft² (1.83 kg/m²)
T = 6000 lb/in. (1050 N/mm)




$$P = (6,000 + 6,000) / 24 \text{ in.} = 500 \text{ psi (34.5 bar)}$$

$$P = (12,000 + 12,000) / 24 \text{ in.} = 1,000 \text{ psi (69 bar)}$$

Note: Little change in weight or thickness
Smooth surface reduces friction & improves flow

Design for Thrust

- Align the fibers along the length of pipe
- Increase/decrease number of layers based on the thrust magnitude



where

$$P = \frac{\rho \pi d^2}{2} \sin \frac{\theta}{2}$$


$$F = \frac{\rho \pi d^2}{4} (1 - \cos \theta)$$

Wet Layup Method

- Carbon fabric saturated with epoxy resin in the field and applied directly to surface of pipe (**Externally** or **Internally**)
- Fabric roll width: 24-48 inch (600-1200mm)
- Fabric thickness: 0.05 inch (1.3 mm)
- For diameters 2 inch (50 mm) and larger
- Applied by packer (small dia.) or by hand
- Used for joint/spot repair or full length
- Creates a pressure vessel inside pipe
- Cures in 24 hours in ambient temperature
- Faster cure is possible by heating
- NSF-61 Approved

Early Applications in 1998

- Paloverde Nuclear Power Plant, AZ
- Prestressed Concrete Cylinder Pipe (PCCP)
- Corrosion of pre-stressing cables
- High design pressures
- Replacement recommended
- CFRP liner installed
- 108 inch (2700mm) Diameter



Wet Layup Process



DC Water – 96-inch (2400 mm) Sewer Repair



Salt River Project - Penstock Construction



Salt River Project – contd.



El Encanto Hydropower, Costa Rica

1750m x 2.1m diameter (July 2009)



Sloped Terrain



**Water seeping into
pipe**



**Leaks continued after cracks were
filled**

El Encanto Hydropower, Costa Rica

1.1 miles x 84-inch diameter (July 2009)

- Four 600x600mm Access Ports
- Poor surface conditions req'd much prep



El Encanto Hydropower, Costa Rica

- Challenge: Not only strengthen but to leak proof
- Total Time: 3 Weeks
- Successful pressurization tests on July 15, 2009



Steel Pipes for Hot Air, Carlsbad, CA

- 42-inch (1070 mm) curved steel pipe
- Galvanic corrosion
- Use glass fabric as dielectric barrier



Tests of Steel Pipes (5-inch Dia.) Pertamina Oil Company, Indonesia



Corroded Steel Pipe in Mine



37TH INTERNATIONAL
NO - DIG
FLORENCE 2019



Wastewater Facility Pipe Repair

City of Atlanta



Wastewater facility Pipe Repair *City of Atlanta – cont'd*




Quality Control

- Record Lot #
- Adhesion Test (ASTM D7234) (200 psi min.)
- Witness Panel (ASTM D3039); 5 glass and 5 carbon FRP coupons



Multi-Layered SuperLaminate™ (Patent Pending)



- **Multi-Axial Reinforcement**
- **Thickness \approx 0.01 -0.025 inch (0.25-0.67mm)**
- **Tensile Strength \approx up to 155,000 psi (1030 MPa)**
- **Infinite combinations of strength & stiffness can be produced**
- **ISO 9000 Certified**




Bridging a Gap in a Pipeline

(Gas Technology Institute)



37TH INTERNATIONAL
NO - DIG
FLORENCE 2019



How do we create a pressurized pipe?

Bridging a Gap in a Pipeline

(600mm Long Gap in 400mm Diam. Pipe)



37TH INTERNATIONAL
NO - DIG
FLORENCE 2019



Two 16-in. diameter pipes with a 24-in. gap



Pressure Testing

on October 16, 2010

- Gas Technology Institute
- Max Operating Pressure = 60 psi (4.1bar)
- Tested to 250 psi (17.2 bar)
- Ultimate Capacity = 900 psi (62 bar)




Field Application

- First Project was completed in Feb 2011
- Client: PSE&G (NJ Gas Utility)
- Contractor: Progressive Pipeline Management
- 2-ft gap in 16" cast-iron pipe
- Winner of 2011 Trenchless Technology *Project of the Year Award*
- Over 60 similar applications




EPA SBIR Grant

- Trenchless Water Main Point Repairs with SuperLaminate
- Phase I Grant -- \$100,000
- May – Oct 2019




USDA Grant for InfnitPipe®

- Phase II Grant -- \$625,000
- Sept 2019 – Aug 2021



Schematic of the in-situ mining process.




Bleaching of Great Barrier Reef



37TH INTERNATIONAL
NO - DIG
FLORENCE 2019

- **Reef lost 50% of its coral cover from 1985-2012**
(Australian Inst. of Marine Science)



Grazie!

Questions?

Mo@QuakeWrap.com

Watch over 120 videos at: [YouTube.com/QuakeWrapInc](https://www.youtube.com/QuakeWrapInc)

Follow us through social media:



QuakeWrap.com



PileMedic.com



PipeMedic.com